

SAFETY DATA SHEET

AVIATION PRODUCTS		Mirror	Image	Re	vision Date	4/4/201
SECTION – 1	CHEMICAL PRODUCT AND COMPANY	IDENTIFICATION	N			
Product Name	Mirror Image				Item MI	
Product Use	Metal Swirl Remover and Light Mai	ntenance				
Company Name	Jet Stream Aviation Products	Office	(972) 542-2400			
	1971 University Business Dr. Suite	102 Fax	(972) 542-0238			
	McKinney Tx 75071	Web	www.jetstreamproducts.c	<u>com</u>		
	EMERGENCY TELEPHONE NUM	BER INFOTR	AC (800) 535-505	i3		
SECTION – 2	HAZARDS INFORMATION					
Physical Hazards F	LAMMABLE LIQUIDS-Category 3					
	YES-Category 2B; SKIN-Category 2; STOT SIN	GLE EXPOSURE-Ca	tegory 3; ASPIRATION-Categ	jory 1		
•	HRONIC-Aquatic Toxicity-Category 4	• .				
Flammable	es Irritant (skin) Narcotic Effects	A:	spiration Toxicity			
	Respiratory Tract Irritar	nt 📢 🚺				
$\mathbf{\vee}$	\mathbf{V}					
	ammable liquid and vapor					
	auses eye irritation, Causes skin irrita Id/or drowsiness or dizziness	tion, May be fata	al if swallowed and ente	ers airways, May cause r	espiratory irrit	ation
	eep away from flames and hot surface	s No smoking	Keen container tightly	closed. Do not get in eve	es or on skin	and
	oid inhalation of mist or vapor, or inh					
ve	ntilated area, Use proper Safety Equ	pment, safety g	lasses, rubber gloves, a	and dust mask, Wash the		
	d water after handling, Avoid release	into the environ	ment, Keep out of read	h of children		
ECTION – 3	COMPOSITION INFORMATION			ted chemicals of composition has	been withheld as a	
						PERCEN
			<u>CAS #</u>	IMPURITIES		
Odorless Mineral S	pirits Isoalkanes C10-C13, Hy		<u>CAS #</u> 68551-17-7	IMPORITIES		
Odorless Mineral S SECTION – 4	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES	drocarbon Solvent	68551-17-7			60 - 909
CHEMICAL NAME Odorless Mineral S SECTION – 4 EYE CONTACT	FIRST AID MEASURES Immediately flush eyes with cold	drocarbon Solvent water for severa	68551-17-7 al minutes while lifting u	upper and lower eyelids,		60 - 909 act
Odorless Mineral S SECTION – 4 EYE CONTACT	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do	drocarbon Solvent water for severa without injury to	68551-17-7 al minutes while lifting u the eye and continue r	upper and lower eyelids, insing, If irritation persist	s seek medic	60 - 909 act al aid
Odorless Mineral S SECTION – 4	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple	drocarbon Solvent water for severa without injury to enty of water, Re	68551-17-7 al minutes while lifting u the eye and continue r	upper and lower eyelids, insing, If irritation persist	s seek medic	60 - 909 act al aid
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical	drocarbon Solvent water for severa without injury to enty of water, Re aid	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate	upper and lower eyelids, insing, lf irritation persist ed clothing and wash befo	s seek medic ore reuse, lf i	60 - 909 act al aid rritation
Odorless Mineral S SECTION – 4 EYE CONTACT	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple	drocarbon Solvent water for severa without injury to enty of water, Re aid	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate	upper and lower eyelids, insing, lf irritation persist ed clothing and wash befo	s seek medic ore reuse, lf i	60 - 90% act al aid ritation
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention	drocarbon Solvent water for severa without injury to enty of water, Re aid have problem br	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of	upper and lower eyelids, insing, If irritation persist ed clothing and wash befo overexposure or feel uny	s seek medic ore reuse, If i well obtain me	60 - 909 act al aid ritation edical
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT INHALATION	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they	drocarbon Solvent water for severa without injury to enty of water, Re aid have problem br person is fully c	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of	upper and lower eyelids, insing, If irritation persist ed clothing and wash befo overexposure or feel uny	s seek medic ore reuse, If i well obtain me	60 - 909 act al aid ritation edical
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT INHALATION INGESTION	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate mediant	water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic	upper and lower eyelids, insing, If irritation persist ed clothing and wash befo overexposure or feel unv out and give one to two g cal emergency, If swallow	s seek medic ore reuse, If in well obtain me glasses of wat red, vomiting	60 - 90' act al aid rritation edical ter to may
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT INHALATION	Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate medical Aspiration into the lungs can cau occur spontaneously, but DO NOT	water for severa without injury to enty of water, Re aid have problem br person is fully c ical attention se severe lung o T INDUCE. If vo	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven	s seek medic ore reuse, If in well obtain me glasses of wat yed, vomiting t aspiration in	60 - 90' act al aid rritation edical ter to may
Odorless Mineral S SECTION - 4 EYE CONTACT SKIN CONTACT INHALATION INGESTION	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate medical Aspiration into the lungs can cau occur spontaneously, but DO NO lungs, Never give anything by medical	water for severa without injury to enty of water, Re aid have problem br person is fully c ical attention se severe lung o T INDUCE. If vo puth to an uncor	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic positing occurs, keep he oscious person. Call a p	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven obysician or hospital eme	s seek medic ore reuse, If in well obtain me glasses of wat yed, vomiting t aspiration in ergency room	60 - 90' act al aid rritation edical eer to may to the
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT INHALATION INGESTION	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate median Aspiration into the lungs can cau occur spontaneously, but DO NO lungs, Never give anything by mediately, If victim is drowsy of	water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If vo outh to an uncor or unconscious a	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he nscious person. Call a p and vomiting, place on t	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven obysician or hospital emer-	s seek medic ore reuse, If in well obtain me glasses of wat ved, vomiting t aspiration in ergency room d down. If pos	60 - 90 act al aid rritation edical eer to may to the sible, do
Ddorless Mineral S ECTION - 4 EYE CONTACT SKIN CONTACT NHALATION NGESTION	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate medical Aspiration into the lungs can cau occur spontaneously, but DO NO lungs, Never give anything by medical	water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If vo outh to an uncor or unconscious a	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he nscious person. Call a p and vomiting, place on t	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven obysician or hospital emer-	s seek medic ore reuse, If in well obtain me glasses of wat ved, vomiting t aspiration in ergency room d down. If pos	60 - 90 act al aid rritation edical eer to may to the sible, do
Ddorless Mineral S ECTION – 4 EYE CONTACT SKIN CONTACT NHALATION NGESTION Aspiration Hazard	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate median Aspiration into the lungs can cau occur spontaneously, but DO NO lungs, Never give anything by mediately, If victim is drowsy of not leave victim unattended and	drocarbon Solvent water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If vo puth to an uncor or unconscious a observe closely	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he nscious person. Call a p and vomiting, place on t	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven obysician or hospital emer-	s seek medic ore reuse, If in well obtain me glasses of wat ved, vomiting t aspiration in ergency room d down. If pos	60 - 90 act al aid rritation edical eer to may to the sible, do
Depress Mineral S ECTION – 4 EYE CONTACT SKIN CONTACT NHALATION NGESTION Aspiration Hazard <u>ACL</u>	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate medical Aspiration into the lungs can cau occur spontaneously, but DO NO lungs, Never give anything by mediately, If victim is drowsy of not leave victim unattended and airways	water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If we puth to an uncor or unconscious a observe closely	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he iscious person. Call a p ind vomiting, place on t for adequacy of breath	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven obysician or hospital emer-	s seek medic ore reuse, If in well obtain me glasses of wat ved, vomiting t aspiration in ergency room d down. If pos	60 - 90' act al aid rritation edical eer to may to the sible, do
Ddorless Mineral S ECTION – 4 EYE CONTACT SKIN CONTACT NHALATION NGESTION Aspiration Hazard <u>ACL</u> Eyes	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate med Aspiration into the lungs can cau occur spontaneously, but DO NO lungs, Never give anything by me immediately, If victim is drowsy of not leave victim unattended and airways JTE SYMPTOMS OF SINGLE OVEREXE	drocarbon Solvent water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If vo puth to an uncor or unconscious a observe closely POSURE discomfort, redr	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he nscious person. Call a p and vomiting, place on t for adequacy of breath	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven obysician or hospital emer-	s seek medic ore reuse, If in well obtain me glasses of wat ved, vomiting t aspiration in ergency room d down. If pos	60 - 90 ^o act al aid rritation edical eer to may to the sible, do
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT INHALATION INGESTION Aspiration Hazard	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical. Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate med occur spontaneously, but DO NO lungs, Never give anything by me immediately, If victim is drowsy on to leave victim unattended and airways JTE SYMPTOMS OF SINGLE OVEREXE Can cause serious eye irritation,	water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If vo outh to an uncor or unconscious a observe closely POSURE discomfort, redr redness, drying	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he nscious person. Call a p and vomiting, place on t for adequacy of breath ness, tearing or cracking	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven obysician or hospital emer-	s seek medic ore reuse, If in well obtain me glasses of wat ved, vomiting t aspiration in ergency room d down. If pos	60 - 909 act al aid rritation edical eer to may to the sible, do
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT INHALATION INGESTION Aspiration Hazard <u>ACL</u> Eyes Skin	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate medical Aspiration into the lungs can cau occur spontaneously, but DO NO lungs, Never give anything by mediately, If victim is drowsy of not leave victim unattended and airways JTE SYMPTOMS OF SINGLE OVEREXER Can cause serious eye irritation, Can cause skin irritation, itching, Mist or vapor may cause mild irrit May be harmful if swallowed, Ma	water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If vo puth to an uncor or unconscious a observe closely COSURE discomfort, redr redness, drying tation, to respira	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he not comiting, place on t for adequacy of breath ness, tearing or cracking tory tract	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven ohysician or hospital eme the left side with the head ing, Can be harmful if sw	s seek medic ore reuse, If in well obtain me glasses of wat red, vomiting t aspiration in ergency room d down. If pos vallowed and	60 - 90 act al aid rritation edical eer to may to the sible, do enters
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT INHALATION INGESTION Aspiration Hazard Eyes Skin Inhalation Ingestion	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate med Aspiration into the lungs can cau occur spontaneously, but DO NO lungs, Never give anything by me immediately, If victim is drowsy of not leave victim unattended and airways JTE SYMPTOMS OF SINGLE OVEREXF Can cause serious eye irritation, Can cause skin irritation, itching, Mist or vapor may cause mild irri May be harmful if swallowed, Ma swallowed and enters airways	drocarbon Solvent water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If we puth to an uncor or unconscious a observe closely POSURE discomfort, redr redness, drying tation, to respira y cause irritation	al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he hascious person. Call a p ind vomiting, place on t for adequacy of breath hess, tearing or cracking tory tract h, of the mouth, throat, a	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven ohysician or hospital eme the left side with the head ing, Can be harmful if sw	s seek medic ore reuse, If in well obtain me glasses of wat red, vomiting t aspiration in ergency room d down. If pos vallowed and	60 - 90 act al aid rritation edical eer to may to the sible, do enters
Ddorless Mineral S ECTION – 4 EYE CONTACT SKIN CONTACT NHALATION NGESTION Aspiration Hazard Eyes Skin nhalation ngestion <u>CHROI</u>	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical. Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate med occur spontaneously, but DO NC lungs, Never give anything by me immediately, If victim is drowsy on to leave victim unattended and airways JTE SYMPTOMS OF SINGLE OVEREXE Can cause serious eye irritation, Can cause skin irritation, itching, Mist or vapor may cause mild irri May be harmful if swallowed, Ma swallowed and enters airways NIC SYMPTOMS OF PROLONGED OR	drocarbon Solvent water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If vo puth to an uncor or unconscious a observe closely POSURE discomfort, redr redness, drying tation, to respira y cause irritation	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he nocious person. Call a p and vomiting, place on t for adequacy of breath ness, tearing or cracking tory tract a, of the mouth, throat, a	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven ohysician or hospital eme the left side with the head ing, Can be harmful if sw	s seek medic ore reuse, If in well obtain me glasses of wat red, vomiting t aspiration in ergency room d down. If pos vallowed and	60 - 90' act al aid rritation edical eer to may to the sible, do enters
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT INHALATION INGESTION Aspiration Hazard Eyes Skin Inhalation Ingestion CHROI Eyes	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical. Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate med occur spontaneously, but DO NO lungs, Never give anything by me immediately, If victim is drowsy or not leave victim unattended and airways JTE SYMPTOMS OF SINGLE OVEREXER Can cause serious eye irritation, itching, Mist or vapor may cause mild irri May be harmful if swallowed, Ma swallowed and enters airways NIC SYMPTOMS OF PROLONGED OR Causes serious eye irritation, recommendation	drocarbon Solvent water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If vo outh to an uncor or unconscious a observe closely POSURE discomfort, redr redness, drying tation, to respira y cause irritation REPEATED OVEI dness, tearing, b	al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he notice person. Call a p and vomiting, place on t for adequacy of breath ness, tearing or cracking tory tract n, of the mouth, throat, a <u>REXPOSURE</u> urning, or pain	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven ohysician or hospital eme the left side with the head ing, Can be harmful if sw	s seek medic ore reuse, If in well obtain me glasses of wat red, vomiting t aspiration in ergency room d down. If pos vallowed and	60 - 90' act al aid rritation edical eer to may to the sible, do enters
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT INHALATION INGESTION Aspiration Hazard Eyes Skin Inhalation Ingestion	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate mediate Aspiration into the lungs can cau occur spontaneously, but DO NO lungs, Never give anything by me immediately, If victim is drowsy of not leave victim unattended and airways DTE SYMPTOMS OF SINGLE OVEREXE Can cause serious eye irritation, Can cause skin irritation, itching, Mist or vapor may cause mild irrit May be harmful if swallowed, Ma swallowed and enters airways NIC SYMPTOMS OF PROLONGED OR Causes serious eye irritation, red Causes skin irritation, itching, red	drocarbon Solvent water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If vo puth to an uncor or unconscious a observe closely COSURE discomfort, redr redness, drying tation, to respira y cause irritation REPEATED OVEI Iness, tearing, b dness, burning, o	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he not comiting, place on t for adequacy of breath ness, tearing or cracking tory tract n, of the mouth, throat, a REXPOSURE urning, or pain drying or cracking	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven ohysician or hospital eme the left side with the head ing, Can be harmful if sw	s seek medic ore reuse, If in well obtain me glasses of wat ved, vomiting t aspiration in ergency room d down. If pos vallowed and	60 - 909 act al aid rritation edical eer to may to the sible, do enters
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT INHALATION INGESTION Aspiration Hazard Eyes Skin Inhalation Ingestion <u>CHROI</u> Eyes	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate mediate mediate and obtain immediate mediate occur spontaneously, but DO NO lungs, Never give anything by mediately, If victim is drowsy of not leave victim unattended and airways ITE SYMPTOMS OF SINGLE OVEREXED Can cause serious eye irritation, itching, Mist or vapor may cause mild irrit May be harmful if swallowed, Ma swallowed and enters airways NIC SYMPTOMS OF PROLONGED OR Causes serious eye irritation, reconstruction, itching, reconstructited item item item item	drocarbon Solvent water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If vo puth to an uncor or unconscious a observe closely COSURE discomfort, redr redness, drying tation, to respira y cause irritation REPEATED OVEI Iness, tearing, b dness, burning, o	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he not comiting, place on t for adequacy of breath ness, tearing or cracking tory tract n, of the mouth, throat, a REXPOSURE urning, or pain drying or cracking	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven ohysician or hospital eme the left side with the head ing, Can be harmful if sw	s seek medic ore reuse, If in well obtain me glasses of wat ved, vomiting t aspiration in ergency room d down. If pos vallowed and	60 - 90 act al aid rritation edical eer to may to the sible, do enters
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT INHALATION INGESTION Aspiration Hazard Eyes Skin Inhalation Ingestion <u>CHROI</u> Eyes Skin Inhalation	Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate medical Aspiration into the lungs can cau occur spontaneously, but DO NO lungs, Never give anything by me immediately, If victim is drowsy of not leave victim unattended and airways JTE SYMPTOMS OF SINGLE OVEREXER Can cause serious eye irritation, Can cause skin irritation, itching, Mist or vapor may cause mild irrit May be harmful if swallowed, Ma swallowed and enters airways NIC SYMPTOMS OF PROLONGED OR Causes serious eye irritation, red Causes skin irritation, itching, red Mist or vapor may cause irritation dizziness or drowsiness	drocarbon Solvent water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If vo puth to an uncor or unconscious a observe closely COSURE discomfort, redr redness, drying tation, to respira y cause irritation REPEATED OVEI Iness, tearing, b dness, burning, o h, to mucus men	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he bacious person. Call a p and vomiting, place on t for adequacy of breath hess, tearing or cracking tory tract h, of the mouth, throat, a REXPOSURE urning, or pain drying or cracking hbranes or respiratory t	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unvo out and give one to two g cal emergency, If swallow ead below hips to preven ohysician or hospital eme the left side with the head ing, Can be harmful if swallow and esophagus, May cau	s seek medic ore reuse, If in well obtain me glasses of wat ved, vomiting t aspiration in ergency room d down. If pos vallowed and	act al aid rritation edical eer to may to the sible, do enters
Odorless Mineral S SECTION – 4 EYE CONTACT SKIN CONTACT INHALATION INGESTION Aspiration Hazard Eyes Skin Inhalation Ingestion <u>CHROI</u> Eyes Skin	pirits Isoalkanes C10-C13, Hy FIRST AID MEASURES Immediately flush eyes with cold lenses if present and easy to do Wash contaminated skin with ple occurs or persists seek medical Move person to fresh air, if they attention DO NOT INDUCE VOMITING. If dilute and obtain immediate mediate mediate and obtain immediate mediate occur spontaneously, but DO NO lungs, Never give anything by mediately, If victim is drowsy of not leave victim unattended and airways ITE SYMPTOMS OF SINGLE OVEREXED Can cause serious eye irritation, itching, Mist or vapor may cause mild irrit May be harmful if swallowed, Ma swallowed and enters airways NIC SYMPTOMS OF PROLONGED OR Causes serious eye irritation, reconstruction, itching, reconstructited item item item item	drocarbon Solvent water for severa without injury to enty of water, Re aid have problem br person is fully c lical attention se severe lung o DT INDUCE. If vo puth to an uncor or unconscious a observe closely COSURE discomfort, redr redness, drying tation, to respira y cause irritation REPEATED OVEI Iness, tearing, b dness, burning, o h, to mucus men	68551-17-7 al minutes while lifting u the eye and continue r emove any contaminate reathing, show signs of onscious, rinse mouth damage and is a medic omiting occurs, keep he bacious person. Call a p and vomiting, place on t for adequacy of breath hess, tearing or cracking tory tract a, of the mouth, throat, a REXPOSURE urning, or pain drying or cracking nbranes or respiratory t a, of the mouth, throat, the	upper and lower eyelids, insing, If irritation persist ed clothing and wash befor overexposure or feel unv out and give one to two g cal emergency, If swallow ead below hips to preven ohysician or hospital eme the left side with the head ing, Can be harmful if sw and esophagus, May cau gract, Symptoms may incl esophagus, and stomach	s seek medic ore reuse, If in well obtain me glasses of wat ved, vomiting t aspiration in ergency room d down. If pos vallowed and use lung dama	60 - 90' act al aid rritation edical eer to may to the sible, do enters age if

Page 2 of 5		Mirror Image		Revision Date	4/4/2017
SECTION – 5 FIRE FIG	HTING MEASURES				
Extinguishing Media	Use DRY chemicals, CO2, alcol	ol foam. Water spra	y to cool or protect exposed	l materials	
Hazardous Decomposition	Burning or thermal decomposition toxic fumes	on can produce, carb	on monoxide, carbon dioxic	le, silicon oxides, and	d other
Reactive With	Reactive with, strong reducing a	gents, strong bases,	strong acids		
Explosion Hazards	Containers may erupt when hea	ted excessively durir	ng a fire		
Static Discharge	Not applicable				
Mechanical Impact	Not applicable				
Protective Equipment	Use MSHA/NIOSH approved se	f-contained breathin	g apparatus and full protect	ive gear	
FLAMMABLE LIQUIDS H	AZARD CLASSIFICATION		NFPA HAZARI	D RATINGS	
Criteria Flash point	t ≥ 37.8°C (100°F) and ≤ 60°C (140°F)		Heal	th 1 🛛 🖊	
NFPA Class II			Flammabili	ty 2 1	
GHS Category	3		Reactivi	ty 0	
WHMIS Class B-3			Special Hazard	ls	\langle / \rangle
					\checkmark
	NTAL RELEASE MEASURES				
Emergency Procedures	Warn personnel of spill				
Personal Precautions	Eliminate ignition sources and v	entilate area, Wear	Personal Protective Equipm	ient, Do not walk thro	ugh spill
Protective Equipment	Safety Glasses, Gloves				
Containment	Use sand or inert non-combusti	ble absorbent pads t	o prevent spill from spreadi	ng, Prevent spill from	entering
Clean Up Procedures	the environment Use wet vacuum or mop and wr	inder to nick up shill	ad matarial than man area y	with cloop water	
Disposal	Dispose of material in accordan				
-		ce with all State and	Federal Guidelines and Re	gulations	
	NG AND STORAGE				
Handling	Keep away from incompatible m equipment, and adequate ventila mist or vapors, May be harmful Wash thoroughly with soap and	ation, Avoid eye and or fatal if swallowed a	skin contact, Avoid inhalation and enters airways, Do not	on of dust, Avoid inha smoke, eat or drink w	alation of
Storage	KEEP OUT OF REACH OF CHI Store away from incompatible m storing in direct sunlight, Store b Category 3)	LDREN, Keep contai aterials, Store away	iner closed when not in use from heat, sparks, open fla	, Keep only in origina mes or hot surfaces,	Avoid
Incompatible Materials	Incompatible with, strong oxidizi	ng agents, strong ba	ses, strong acids		
•	RE CONTROLS / PERSONAL PROTE		,		
EXPOSURE LIMITS					Significar
CHEMICAL NAME	ACGIH (TWA 8)	ACGIH (STEL)	OSHA PEL (TWA 8)	OSHA (CEIL)	Exposure
Odorless Mineral Spirits	None Established	, , ,	· · · ·	· · · · ·	•
PERSONAL PROTECTIVE E					
		P		Ť	
Chemical Safety Glasses, Goggles or Face Shield	Impervious Dust M Chemical Gloves	ask		Eye W (Recomm	
Ventilation				HMIS HAZARD	RATINGS
General Ventila				Health	1
If exposure limit	s listed above are exceeded, or irri	tation is experienced	1,	Flammability	2

If exposure limits listed above are exceeded, or irritation is experienced, use a MSHA / NIOSH approved dust mask or respirator

Flammability 2 Reactivity 0 Personal Protection E

Page 3 of 5			Mirror Image		Revi	sion Date	4/4/2017
SECTION – 9 PH	IYSICAL AND CHEM	CAL PROPERTIES					
Flash Point	39.4 - 60ºC (101 - 1	40⁰F) - TAG Closed Cup	Speci	fic Gravity / Density	1.283		
Flammable Limits	Lower 0.7%, Upper	5.0%	pH (±	0.3)	NA		
Auto-Ignition Temp.	230°C (446°F)		Visco	sity	4.1 cSt @ 20 °C		
Physical State	Liquid		Freez	e Point	-68°C (< -90°F)		
Appearance	Light Grey		Boilir	ng Point	239 - 276°C (464	4 - 528°F)	
Odor	Light Solvent		Vapo	r Density (air=1)	ND		
Odor Threshold	ND		Vapo	r Pressure (mmHg)	0.02 mm Hg @ 2	20°C	
Solubility	< 1%		Evapo	oration Rate (nBuAc=	=1) ND		
Volatiles	< 80%		Partit	ion Coefficient	ND		
VOC	< 80%		~ 157.52				
LVP-VOC	0.0%		Deco	mposition Temperatu	ire ND		
SECTION – 10 S	TABILITY AND REAC	ΤΙVITY					
Reactivity (Specific Test D	ata) None avail	able					
Chemical Stability	Stable at n	ormal ambient temper	rature and pressure	Э			
Hazardous Polymeriz		-					
Conditions To Avoid	Incompatib	le materials					
Incompatible Material	s Incompatib	le with, strong oxidizir	ng agents, strong b	ases, strong acids			
Thermal Decompositi	on Burning or toxic fumes	thermal decompositio	n can produce, ca	bon monoxide, cart	oon dioxide, silicon d	oxides, and	other
SECTION – 11 TO	OXICOLOGICAL INFO	ORMATION					
ROUTES OF EXPOSU	RE						
Eyes (Yes), Skin (Ye	s), Ingestion (Yes),	Inhalation (Yes "Vapo	or, Fumes or Dust")			
	,			,			
Eyes		s eye irritation, discom	_	na			
Skin		itation, itching, rednes		-			
Inhalation		cause mild irritation, t		.9			
Ingestion		swallowed, May cause		outh, throat, and es	ophagus, May caus	e lung dama	age if
CHRONIC		OLONGED OR REPEA	TED OVEREXPOSU	<u>RE</u>			
Eyes	Causes serious e	e irritation, redness, t	earing, burning, or	pain			
Skin	Causes skin irritat	ion, itching, redness,	burning, drying or o	cracking			
Inhalation	Mist or vapor may dizziness or drows	cause irritation, to mu	ucus membranes o	r respiratory tract, S	symptoms may inclu	de, headacl	ne,
Ingestion		swallowed, May cause ters airways, Symptor /stem depression					
Acute Tox Calculated		> 5,000 mg/kg	Dermal:	> 5,000 mg/kg	Inhaled:	> 5.0 mg	g/L
Acute Tox Category	Not applicable (Oral	>5000 mg/kg), Not appli	cable (Dermal >2,000	0 mg/kg), Not applicab	le (Inhaled >5 mg/L) D	oust or Mist	
Additional Info							
Target Organs		Eyes (Lens or cornea					
Medical Conditions Notes to Physician		skin, central nervous s damage may contrai		-		-	
	cause aspiration p	u		gastie lavage, com			y
CARCINOGENIC – Th		concentrations above (
CHEMICAL NAME	<u>NTP</u>	ACG	IH	IARC		Category	
None Listed	NA	NA		NA	NA		
		CTS – This product con	tains concentration				
CHEMICAL NAME	<u>Germ Cell M</u>	utagenicity		Toxic to Repro	duction		
None Listed				NA			
COMPONENTS ACUT		-	0.11	Beerking	-	0110 -	
CHEMICAL NAME	Type		Subject	Result Value	Exposure Time	<u>GHS Ca</u>	
Odorless Mineral Spirit	ts LD50 LC50		Rat Rat	> 5,000 mg/kg > 20 mg/L	4 Hours (Vapor)		mg/kg) mg/L)
	LD50		Rabbit	> 20 mg/L > 5,000 mg/kg	+ riouis (vapor)		mg/L) mg/kg)
	2000	201110		_,		,- 2000	

Page 4 o	of 5			Mirror	Revision Date	4/4/2017				
SECTION	– 12 EC	OLOGICAL INF	ORMATION							
CHEMIC/	AL NAME	-	<u>Type</u>	Subject Subject La	<u>tin</u>	Result Value	<u>Exposure</u>	<u>Time</u> <u>GH</u>	S Category	
Odorless	Mineral Spirits		LD50	Rainbow Trout (Oncorhyno	, ,	> 1,000 mg/l		- (>100 mg/L)	
		E	EC50	Water Flea (Daphnia m	agna)	> 1,000 mg/l	- 48 Hou	rs 4 (>100 mg/L)	
	nce And Degr	-		is inherently biodegrada		•	finition			
	nulative Pote	•		vidence to suggest bioa		will occur				
Mobility In Soil This material is a partially mobile liquid										
	verse Effects		-	ful to aquatic life						
SECTION		POSAL CONSI								
				E GROUND, OR INTO A						
•	•		nce with all	I State and Federal Gui	dennes and	Regulations				
	CRA rules i		sibility of the	e user of the product to a	latarmina a	t the time of dispo	al whathar	the material is	a hazardous	
waste	CIA Tules, I	is the respons	Sidility of the		etermine, a		sai, whether	the material is	a Hazaruous	
Chemica	al additions,	processing or c	otherwise al	tering this material may	make the wa	aste management	information	presented in th	is SDS	
		te, or otherwise				0				
SECTION	– 14 TR	ANSPORT INFC	ORMATION							
DOT CL	ASSIFICATI	N								
UN Nur	<u>mber</u>			Proper Shippir	g Name n.o.	s. (Chemicals) or "	Limits"			
Ltd C	Qty			"Limited Quantity"	n.o.s.(Od	orless Mineral Spi	rits)			
Hazard C	Class Packin	<u>g Group</u>	Label Code	es Reportable Qu	<u>antity (lbs)</u>	<u>Response</u> <u>Mari</u>	ne Pollutant	Hazard Label	<u>Secondary</u>	
COMB L	LQD P	G III	None	None	;	128	No			
Additiona	Additional Info: Classified as a combustible liquid as per 49 CFR 173.120(b)(2) for DOT (Flash Point: >100°F and <200°F), For flammable liquids in Packing Group III and combustible liquids, inner packagings not over 5.0 L (1.3 gallons) net capacity each, packed in a strong outer packaging.									
IATA CL		ION								
UN Nu		—		UN Proper Shipping Nam	<u>e</u> <u>n.o.s. (Ch</u>	emicals) or "Limi	<u>s"</u>			
UN 19	993			Flammable Liquid, n.o.	s. (Odorless	Mineral Spirits)				
<u>Class</u>	Packing Gro	up Enviro Haz	ard ERG	Special Provisions	Labels [Required	Subsidiary	<u>Risk</u> <u>Ha</u>	zard Label	
3	III	No	3L		Flamma	ble Liquid	-			
Special p	precautions /	marking:				-			FLAMMABLE LIQUID	
		-							3	

Page 5	5 of 5			Mir	ror Imag	e				Re	evision Da	t e 4/	/4/2017
SECTIO	ON – 15 REGULATOF	RY INFORMATION											
TSCA													
		Sec 8(b) Inv	ventory	Sec 8(d)	Health An	d Safetv	s	ec 4(a) Chem	ical Test	Rules	Sec 12/h) Export Not	tification
		. ,	•	000 0(0)		a outery	0			i uico	000 12(5		inoution
	ess Mineral Spirits	Yes)		Fusianian	Develoption				
	TABLE QUANTITIES		tremely Hazar			Reportable C	•	Emission	• •	•			
CHEMI		EPCRA TPQ	Sec 302 EP	CRA RQ Se	c 304 C	ERCLA RQ	Sec 103	TRI Se	ec 313	RCI	RA Code	RMP TQ	Sec 112
None	Listed												
<u>SARA</u>		Sect	ion 311				Secti	on 311 / 31	2 Hazar	ds			
CHEMI	CAL NAME	Hazardo	us Chemica	I	Acute	C	Chronic	Fla	mmable	F	Pressure	Rea	active
Odorle	ess Mineral Spirits		Yes						Yes				
RIGHT	TO KNOW					STATE							
CHEMI	CAL NAME	CA	CT FL	IL	LA	NJ	NY	PA	МІ	MN	MA	RI	wı
Odorle	ess Mineral Spirits					Yes		Yes					
CALIFO	•		WAF	NING! TI	his produ		ns chen	nicals knov	vn to the	e state o	f Californi	ia to caus	e:
		CAS #		h Defects	•	Reproduc			Carcine			evelopme	
None I		040 #	Birt	Dereote	,	Reproduce			Garoni	ogen	D	evelopine	intai
			CL	ean Air Ao						Cloop W	ater Acts		
		CAC #					0						TD
		CAS #	HA	AP	Ozone	e Class 1	UZO	ne Class 2		HS	PP		TP
	ess Mineral Spirits	68551-17-7								s (Oil)			
	NATIONAL REGULATIONS	- ·						ntories of th	ne followi	-			
CHEMI		Australi	а	Canada	Eu	rope (EIN	ECS)	Japan		Ko	orea	U	K
None I	Listed												
<u>WHMIS</u>	Classification												
CHEMI	CAL NAME		DSL Cla	iss Des	cription								
None I	Listed												
SECTIC	ON – 16 OTHER INFOR	RMATION											
<u>SDS</u>	LEGEND DESCRIPTION												
~	Approximately				*	Additiona	al Informa	tion					
	American Conference of Gover		gienists		LC50			at is lethal to		• ·	•		
CAS CEIL	Chemical Abstracts Service Re Ceiling Limit (15 minutes)	gistry			LD50 LEL	Lower Ex		to 50% of a g	given spec	cies by a g	given route o	t exposure	
	Comprehensive Environmental	Response, Compens	ation, and Liat	oility Act	LD	Liver Da	•						
CI	Cochlear Impairment				NA	Not Appl	-						
CNS	Central Nervous System				ND	Not Dete							
EC50 EPA	Concentration of a chemical that Environmental Protection Agen	-	esponse		NE NFPA	Not Esta		ection Associa	ation				
Eye	(EI = Irritation) (ED = Damage)	•	ent)		NIOSH			or Occupation		and Heal	th		
FBG	Full Bunker Gear	(,		NTP			y Program					
GHS	Globally Harmonized System				OSHA	Occupati	onal Safe	ety and Health	n Administ	ration			
HAP	California Hazardous Air Polluta	ant Clean Air Act			PEL			sure Limit (OS	SHA)				
	Safety glasses				PNS			s System					
	Safety glasses, gloves				PP REL			Pollutant und		an Water	Act		
	Safety glasses, gloves, chemica Face shield, gloves, chemical a	-			RT	Upper Re		posure limit (Tract	NIOSH)				
	Safety glasses, gloves, dust res	-			Skin			D = Damage)	(SA = Abs	sorption) (SS = Sensit	izer)	
	Safety glasses, gloves, chemica	-	or		SARA			ments and R	·	• •		,	
HMIS-G	Safety glasses, gloves, vapor re	espirator			STEL	Short Te	rm Expos	ure Limit (15	minutes)				
	Splash goggles, gloves, chemic		ator		TC Lo			tion that is to	-	-	s in a given	time	
	Safety glasses, gloves, dust an				TD Lo			s toxic to a gi		es			
	Splash goggles, gloves, chemic	-						alue (ACGIH)		· \//ot ^	at		
	Air line hood or mask, gloves, fi	uii chemical suit, boot	b		TP			ollutant under Control Act	the Clear	i vvater A	CI		
HMIS-X HS	Ask Supervisor California Hazardous Substanc	e under the Clean Wa	ter Act		TSCA TWA			verage (8 hou	ırs)				
KD	Kidney Damage (nephropathy)				UEL	Upper Ex	-		-,				
lot Stro	am Aviation Products					-							

and nCites LLC have compiled the information herein from sources believed to be reliable and up-to-date, and is accurate to the best of our knowledge. However, we cannot give any guarantees regarding information from other sources or the completeness and expressly do not make warranties, nor assume any liability for its use. The information contained herein is provided for reference purposes only and is intended only for persons having relevant technical skills. Because conditions and manner of use are outside of our control, the user is responsible for determining the conditions of safe use of the product. Buyers and users assume all risk, responsibility and liability whatsoever for any and all injuries, losses, or damages to persons or property arising from the use of this product or information.